

2017-1773
2018-04-19

X-CIDE 107W

INDUSTRIAL LIQUID BACTERICIDE

**READ LABEL BEFORE USING
FOR USE IN INDUSTRIAL PROCESSES ONLY.
NOT FOR DOMESTIC USE.**

ACTIVE INGREDIENT:

Glutaraldehyde	20.0%
Oxydiethylene bis-(alkyl*dimethyl ammonium chloride)	5.0%
*alkyl distribution as derived from coconut fatty acids.	

CAUTION

POISON

FLAMMABLE

CORROSIVE

**DANGER
SEVERE SKIN AND EYE IRRITANT
KEEP OUT OF REACH OF CHILDREN**

SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS

Distributed by:

BAKER HUGHES CANADA COMPANY
GULF CANADA SQUARE, 1000-401 9th AVE. SW
CALGARY, AB T2P 3C5

Telephone Number for Information: (403) 537-3850

EMERGENCY CONTACT (24 HOURS PER DAY) 800-231-3606

**REGISTRATION NO. 24998
PEST CONTROL PRODUCTS ACT**

NET CONTENTS: 18 Liters – 3000 Liters

PRECAUTIONS

KEEP OUT OF REACH OF CHILDREN

Corrosive, causes irreversible eye damage and skin irritation. Harmful or fatal if swallowed. Do not get in eyes, on skin or clothing. When handling this concentrate wear goggles or face shield, chemical-resistant gloves, long pants, a long-sleeved shirt, and shoes plus socks. Remove contaminated clothes and shoes. Avoid contamination of food.

ENVIRONMENTAL HAZARDS

This product is toxic to birds, fish, and other aquatic organisms. It is not to be used in circumstances that would cause or allow it to enter lakes, streams, ponds estuaries, oceans or other waters in contravention of federal or provincial regulatory requirements. Do not discharge effluent containing this product into sewer systems without previously notifying the sewage treatment plant authority. The requirements of applicable laws should be determined before using the product.

FIRST AID

IF IN EYES: Hold eye open and rinse slowly and gently with water for 15-20 minutes. Remove contact lenses, if present, after the first 5 minutes, then continue rinsing eye. Call a poison control centre or doctor for treatment advice.

IF ON SKIN OR CLOTHING: Take off contaminated clothing. Rinse skin immediately with plenty of water for 15-20 minutes. Call a poison control centre or doctor for treatment advice.

IF INHALED: Move person to fresh air. If person is not breathing, call 911 or an ambulance, then give artificial respiration, preferably by mouth-to-mouth, if possible. Call a poison control centre or doctor for further treatment advice.

IF SWALLOWED: Call a poison control centre or doctor immediately for treatment advice. Have person sip a glass of water if able to swallow. Do not induce vomiting unless told to do so by a poison control centre or doctor. Do not give anything by mouth to an unconscious person. Take container, label or product name and Pest Control Product Registration Number with you when seeking medical attention.

TOXICOLOGICAL INFORMATION

Probable mucosal damage may contraindicate the use of gastric lavage. Measures against circulatory shock, respiratory depression and convulsion may be needed. Avoid alcohol. Treat symptomatically.

NOTICE TO USER: This pest control product is to be used only in accordance with the directions on the label. It is an offence under the *Pest Control Products Act* to use this product in a way that is inconsistent with the directions on the label.

DIRECTIONS FOR USE

X-CIDE 107W is recommended for use in industrial, nonpotable waters where a bactericidal problem is clearly demonstrated. Specifically, **X-CIDE 107W** is intended for use in water treating systems from petrochemical and oilfield operations, and for treating tank bottoms water where petroleum hydrocarbons are stored.

OILFIELD AND PETROCHEMICAL SYSTEMS

TREATMENT:

X-CIDE 107W can be used either in slug treatment or in continuous application. Dosages may vary from 500 ppm of **X-CIDE 107W** in slug application to 20 ppm of **X-CIDE 107W** in continuous treatment. For slug treatments, add up to 500 ppm of **X-CIDE 107W** at intervals to the water system to establish control and to prevent regrowth of bacterial slime.

This method is particularly suitable for control of bacteria in storage tank bottom sediments. For continuous treatment, inject 20 to 200 ppm of **X-CIDE 107W** at a point where good mixing can be assured. Technical advice can be obtained from your Baker Petrolite Sales Engineer.

STORAGE

Do not use, pour, spill, or store near heat or open flame.

DISPOSAL

1. Triple or pressure-rinse the empty container. Add the rinsings to the treatment site.
2. Follow provincial instructions for any required additional cleaning of the container prior to its disposal.
3. Make the empty container unsuitable for further use.
4. Dispose of the container in accordance with provincial requirements.
5. For information on the disposal of unused, unwanted product, contact the manufacturer or the provincial regulatory agency. Contact the manufacturer and the provincial regulatory agency in case of a spill and for clean-up of spills.

Read Product Safety Data Sheet prior to use. PRODUCT WARRANTY, DISCLAIMER AND LIMITATION OF LIABILITY ARE FOUND on the Product Safety Data Sheet. Unless inconsistent with applicable law, use of Product signifies agreement with these provisions.

REV 03/17